RESPONSE TO REQUEST FOR ADDITIONAL REVIEW

MAINTENANCE DETROIT METROPOLITAN WAYNE COUNTY AIRPORT

PREPARED FOR THE JOINT LEGISLATIVE SELECT COMMITTEE ON THE WAYNE COUNTY DETROIT METROPOLITAN AIRPORT

The Honorable Glenn D. Steil
Michigan Senate
Co-Chairperson, Joint Legislative Select Committee
1020 Farnum Building
Lansing, Michigan
and
The Honorable James L. Koetje
Michigan House of Representatives
Co-Chairperson, Joint Legislative Select Committee
N1093 House Office Building
Lansing, Michigan

Dear Senator Steil and Representative Koetje:

This special report is in response to your June 6, 2000 letter requesting a more detailed review of the Detroit Metropolitan Wayne County Airport (the Airport). This special report contains our responses to specific requests in the general issue area of Airport maintenance.

Specifically, you have asked us if the observations noted in your request were accurate and supported by the material in the preliminary review. Also, you asked us to conduct a more detailed review of the internal control weaknesses identified in the preliminary review and to identify any significant losses that may have occurred at the Airport.

Our procedures were of limited scope. Therefore, our review should not be considered an audit in accordance with *Government Auditing Standards* issued by the Comptroller General of the United States.

We are available to present this special report to the Joint Legislative Select Committee on the Wayne County Detroit Metropolitan Airport upon request. If this is the Committee's desire or if you have any questions or concerns regarding this review, please contact me.

Sincerely,

Thomas H. McTavish, C.P.A. Auditor General

This page left intentionally blank.

TABLE OF CONTENTS

MAINTENANCE DETROIT METROPOLITAN WAYNE COUNTY AIRPORT

| Report Letter | 1 4 |
|--|--------|
| | 4 |
| Overview of Airport Maintenance Supplies | |
| Scope of Review | 4 |
| Comments | 4 |
| Exhibits* | |
| Exhibit A - Power Plant Inventory | 9 |
| Exhibit B - Equipment Repair Inventory | 10 |
| Exhibit C - Airport Response | 11 |

^{*} All exhibits of the Wayne County Detroit Metropolitan Airport Preliminary Review Reports are available by contacting the Office of the Auditor General in writing and specifying the exact exhibits that you would like to receive. Your written request, with your name and address, must be sent to: The Office of the Auditor General, 201 N. Washington Square, 6th Floor, Lansing, Michigan, 48913.

OVERVIEW OF AIRPORT MAINTENANCE SUPPLIES

The Detroit Metropolitan Wayne County Airport maintains inventories of maintenance supplies that are stored in inventory cribs located in the power plant, field maintenance, building maintenance, and equipment repair areas.

Maintenance supplies are requisitioned by maintenance personnel to fill work order needs. Replacement supplies are purchased either from the county store or on dollar-limited blanket purchase orders held with local businesses. The county store is a supply warehouse located in the county maintenance yard adjacent to the Airport.

The Airport expended approximately \$4.8 million on maintenance supplies in each of fiscal years 1999-2000 and 1998-99.

SCOPE OF REVIEW

Our procedures were of limited scope. Therefore, our review should not be considered an audit in accordance with *Government Auditing Standards* issued by the Comptroller General of the United States.

We reviewed the existing internal control over the maintenance supply inventories. Also, we selected items from existing maintenance supply inventory records and conducted a physical inventory count of the items.

COMMENTS

Request:

Are the observations noted in the letter from the Joint Legislative Select Committee on the Wayne County Detroit Metropolitan Airport accurate and supported by the material in the preliminary review?

Committee Observations:

In its June 6, 2000 letter, the Committee observed that the Preliminary Review of Maintenance reported that the Airport has 253 maintenance employees, providing

maintenance for areas such as the power plant, the airfield, buildings, and equipment repair. Airport maintenance expenditures for fiscal year 1997-98 totaled \$28.3 million (20% of total Airport expenditures). The report indicates that the Airport did not list maintenance supplies used on nonrecoverable work orders (i.e., requests for maintenance that is the Airport's responsibility) because the Airport ". . . did not consider listing maintenance supplies on nonrecoverable work orders as being cost effective."

The report also indicates that the Airport expended \$3.3 million on maintenance supplies in fiscal year 1997-98. However, the report indicates that the Airport's procedures for recording the receipt and disbursement of maintenance supplies and for conducting annual physical inventories are in draft form and have not been promulgated. Further, the report reveals that the Airport's field maintenance and building maintenance areas did not maintain inventory records. In addition, the power plant, field maintenance, building maintenance, and equipment repair areas did not conduct annual physical inventories.

Procedure:

We reviewed the Committee's letter and compared it with our preliminary report and working papers to determine if the letter was accurate and supported by the preliminary report.

Comment:

The aforementioned observations of the Committee are accurate and supported by the material in the preliminary review.

Request:

Conduct a detailed review to determine whether the internal control weaknesses in the preliminary review resulted in significant losses to the Airport.

Procedure:

We reviewed the existing internal control over maintenance supply inventories.

Comment:

The Airport's internal control over maintenance supplies was weak and, in some cases, nonexistent. For example, our review noted the following internal control weaknesses:

1. The Airport does not maintain inventory records for all maintenance supplies. The power plant and equipment repair areas are the only areas in which inventory

records are kept. The field maintenance and building maintenance areas do not maintain inventory records. The field maintenance and building maintenance areas store items such as carpentry supplies (i.e., tools, plywood, dry wall, ceiling tile, and carpet), fencing, seating, and plumbing and electrical supplies.

- 2. The field maintenance and building maintenance areas are not staffed by stores clerks. Employees have open access to supplies.
- 3. Although stores clerks staff the power plant and equipment repair areas, managers, foremen, and supervisors have access to supplies when the stores clerks are absent.
- 4. There is no separation of duties for the receipt, receipt posting, and disbursement of maintenance supplies in the power plant area. The same stores clerk in the power plant area performs all of the functions of receipting, posting, and disbursing maintenance supplies.
- 5. The Airport does not monitor nonrecoverable work orders. The Airport does not require that nonrecoverable work orders include the cost of maintenance supplies, which would enable the Airport to monitor the costs of certain maintenance projects.
 - Also, nonrecoverable work order projects with priority 1 through 3 (1 immediate attention, 2 public inconvenience, 3 normal maintenance) are not approved by supervisory personnel to ensure that only the maintenance supplies needed for a particular project are disbursed to maintenance personnel.
- 6. The Airport does not conduct periodic physical inventory counts. Physical inventory counts are not conducted in the power plant, field maintenance, building maintenance, and equipment repair areas. However, because inventory records are not maintained for the field maintenance and building maintenance areas, physical inventory counts would be of little value to the Airport.

Maintaining an appropriate level of internal control over inventories safeguards assets by helping to minimize the possibility that errors or irregularities could occur and not be detected in a timely manner.

Procedure:

We tested the accuracy of existing maintenance supplies inventory records in the two areas (power plant and equipment repair) that maintained inventory records (see Exhibits A and B).

Comment:

The balances recorded in the inventory records were generally overstated. For example, we conducted a physical inventory of 51 supply items located in the power plant area (see Exhibit A). Items inventoried consisted of air conditioners, pumps, motors, heaters, parts, and parts assemblies. The total recorded value of the items inventoried was \$30,945. The total value of items counted was \$30,026. The recorded value of the power plant supplies was overstated by \$919 (3%).

We also conducted a physical inventory of 52 supply items located in the equipment repair area (see Exhibit B). Items inventoried consisted of vehicle parts. The total recorded value of the items inventoried was \$20,450. The total value of items counted was \$12,100. The recorded value of the equipment repair supplies was overstated by \$8,350 (69%).

The overstatement of inventory supply records noted in our physical inventory count in the power plant and equipment repair areas could be an indication of unauthorized activity.

Costs for supply items in both areas were not posted on the individual inventory records. Airport staff had to obtain the costs from vendor invoices or catalogs. This process delayed completing our physical inventory of both areas for approximately four weeks.

Inventory records in the field maintenance and building maintenance areas were not maintained. Thus, conducting physical inventories in those areas would have served no purpose. Therefore, we could not determine whether any significant losses occurred in these areas. The lack of any inventory records in the field maintenance and building maintenance areas presents a significant risk for unauthorized activity.

In conclusion, weak internal control over the maintenance supply inventory as described in this review greatly increased the risk of inventory shrinkage.

Airport Response:

The draft report was shared with the Airport on November 20, 2000. The Airport indicated that the report is an accurate portrayal of the Airport's inventory control for the Maintenance Division. However, the Airport felt that the report should also highlight the areas in which the Maintenance Division is moving toward correcting these deficiencies. These areas are highlighted in the Airport's response presented in Exhibit C.

POWER PLANT INVENTORY

| Sample Item | Part | | On-Hand | On-Hand | lt | tem | Recorded | Actual | |
|-------------|---------------|--------------------------------------|----------|---------|-----|-------|--------------|-----------|------------|
| Number | Number | Item Description | Recorded | Counted | | ost | <u>Value</u> | Value | Difference |
| 1 | WAC053 | 5200 B.T.U./Hr. Air conditioner | 13 | 13 | \$ | 219 | \$ 2,847 | \$ 2,847 | \$ 0 |
| 2 | ADU18/ASU18 | Air conditioner | 1 | 1 | \$1 | ,314 | 1,314 | 1,314 | 0 |
| 3 | D-9175D-1014 | Mondutrol 4 motor actuator | 1 | 1 | \$ | 427 | 427 | 427 | 0 |
| 4 | 060-81191-060 | Actuator lever | 2 | 2 | \$ | 35 | 70 | 70 | 0 |
| 5 | 189120 | Bearing assembly | 4 | 4 | \$ | 128 | 512 | 512 | 0 |
| 6 | R-2080-1 | Booster | 6 | 6 | \$ | 52 | 312 | 312 | 0 |
| 7 | N/A | Large cabinet | 1 | 1 | \$ | 477 | 477 | 477 | 0 |
| 8 | N/A | Door halves with lock | 2 | 2 | \$ | 550 | 1,100 | 1,100 | 0 |
| 9 | 12005 | Capacitor | 1 | 1 | \$ | 4 | 4 | 4 | 0 |
| 10 | NAB71 | Wall case for zone line a.c. units | 3 | 3 | \$ | 64 | 191 | 191 | 0 |
| 11 | E5187B | Compressor | 2 | 2 | \$ | 380 | 761 | 761 | 0 |
| 12 | V16501 | Compressor | 1 | 1 | \$ | 166 | 166 | 166 | 0 |
| 13 | NT-10 | Warm air limit control | 3 | 3 | \$ | 79 | 236 | 236 | 0 |
| 14 | T-9001-1 | Fluidic receiver controller | 4 | 1 | \$ | 230 | 921 | 230 | (690) |
| 15 | C-208-2 | Cumulator | 1 | 1 | \$ | 86 | 86 | 86 | ` o´ |
| 16 | D-251-405 | Damper motor | 1 | 1 | \$ | 61 | 61 | 61 | 0 |
| 17 | A-17229 | Drier . | 2 | 2 | \$ | 32 | 64 | 64 | 0 |
| 18 | MR60-CPO | Plastic drum pump | 1 | 1 | \$ | 19 | 19 | 19 | 0 |
| 19 | A-4000-601 | Filter air drier | 1 | 1 | \$ | 172 | 172 | 172 | 0 |
| 20 | 8-140211 | 1 hp Motor | 1 | 1 | \$ | 99 | 99 | 99 | 0 |
| 21 | 52 | 1/15 hp Motor | 10 | 10 | \$ | 46 | 460 | 460 | 0 |
| 22 | BG111044 | 1/2 hp Motor | 1 | 1 | \$ | 564 | 564 | 564 | 0 |
| 23 | Euclid Green | Paint | 7 | 7 | \$ | 35 | 244 | 244 | 0 |
| 24 | V11HAA-100 | Solenoid | 31 | 31 | \$ | 64 | 1,984 | 1,984 | 0 |
| 25 | RP670A-1001 | Pneumatic relay switch | 2 | 2 | \$ | 32 | 63 | 63 | 0 |
| 26 | JC-5361 | Test probe | 13 | 13 | \$ | 13 | 167 | 167 | 0 |
| 27 | HO6E-36 | 36" Long thermocoupler | 31 | 31 | \$ | 5 | 169 | 169 | 0 |
| 28 | EPT-102-1 | 12 Volt transducer | 10 | 10 | \$ | 402 | 4,016 | 4,016 | 0 |
| 29 | 198162EA | Transformer | 1 | 1 | \$ | 50 | 50 | 50 | 0 |
| 30 | B-3AR | Trap | 5 | 12 | \$ | 65 | 326 | 783 | 457 |
| 31 | F-22 | 22 psi Valve | 3 | 1 | \$ | 127 | 382 | 127 | (255) |
| 32 | 5051-01 | Valve assembly | 7 | 7 | \$ | 83 | 581 | 581 | O O |
| 33 | 5454FX | Vibration eliminator | 2 | 2 | \$ | 31 | 62 | 62 | 0 |
| 34 | 20-150-00 | Water gage | 5 | 5 | \$ | 38 | 192 | 192 | 0 |
| 35 | T-800-1605 | Brass 6 1/2" well | 1 | 1 | \$ | 25 | 25 | 25 | 0 |
| 36 | N/A | 8" Standard twist wirewheel | 4 | 4 | \$ | 18 | 72 | 72 | 0 |
| 37 | AZ22E15D5B | Zone line air conditioner - slide in | 2 | 2 | \$ | 802 | 1,605 | 1,605 | 0 |
| 38 | 3405-21 | Actuator - motor | 9 | 9 | \$ | 245 | 2,203 | 2,203 | 0 |
| 39 | 875778 | Cart parts - motor | 3 | 3 | \$ | 557 | 1,671 | 1,671 | 0 |
| 40 | H-3610-1002 | Controller - humidity | 3 | 3 | \$ | 209 | 627 | 627 | 0 |
| 41 | BLF1A | Cooler - bottled water | 1 | 1 | \$ | 192 | 192 | 192 | 0 |
| 42 | AP317 | Filter/water - drinking water line | 19 | 19 | \$ | 21 | 397 | 397 | 0 |
| 43 | N/A | Gasket - manhole 17" x 13 1/2" | 7 | 6 | \$ | 26 | 180 | 154 | (26) |
| 44 | MMHD1502TA | Heater - air 1500w | 15 | 14 | \$ | 35 | 521 | 486 | (35) |
| 45 | 11USHS100 | Heater - unit heater | 4 | 4 | \$ | 590 | 2,360 | 2,360 | ` o´ |
| 46 | 3001AA5097 | Heater - exhaust fan | 1 | 1 | \$ | 580 | 580 | 580 | 0 |
| 47 | LFP6152 | Heater - portable electric | 2 | 1 | \$ | 129 | 257 | 129 | (129) |
| 48 | APR 10040 | Insulation - 48"x35'X1 | 3 | 2 | \$ | 237 | 710 | 473 | (237) |
| 49 | 140-0514 | Paint - flat black spray can | 7 | 4 | \$ | 2 | 11 | 6 | (5) |
| 50 | N/A | Praire gold 1 gallon | 10 | 10 | \$ | 36 | 360 | 360 | 0 |
| 51 | 992238 | Regulator - pump | 1 | 1 | \$ | 75 | <u>75</u> | <u>75</u> | 0 |
| | | | | | | Total | \$ 30,945 | \$30,026 | \$ (919) |
| | | | | | | | | | |

N/A = Not available.

EQUIPMENT REPAIR INVENTORY

| Sample Item | Part | Itara Dagarintian | On-Hand | On-Hand | tem | | corded | | ctual | D:4 | fa |
|-------------|---------------|-------------------------------|----------|---------|-----------|----|--------|------------|-------|-----|----------|
| Number | Number | Item Description | Recorded | Counted | ost | | /alue | | alue | | ference_ |
| 1 | 2602428 | Motor/salt spreader | 5 | 5 | 116 | \$ | 578 | \$ | 578 | \$ | 0 |
| 2 | 3908560 | Pulley (alternator) trackless | 3 | 3 | \$ 20 | | 60 | | 60 | | 0 |
| 3 | SA776 | Starter motor | 3 | 1 | \$ 116 | | 349 | | 116 | | (233) |
| 4 | 78DT | Battery | 15 | 5 | \$ 67 | | 999 | | 333 | | (666) |
| 5 | A710C | Air filter | 6 | 6 | \$ 32 | | 193 | | 193 | | 0 |
| 6 | AR4518401RX | Pump | 4 | 1 | \$ 142 | | 569 | | 142 | | (427) |
| 7 | 53008647 | Jeep alternator | 4 | 4 | \$ 126 | | 504 | | 504 | | 0 |
| 8 | E7VY19703A | Compressor | 1 | 1 | \$ 185 | | 185 | | 185 | | 0 |
| 9 | 56006551 | Filter | 7 | 4 | \$ 273 | | 1,908 | | 1,090 | | (818) |
| 10 | GR-821 | Ford Explorer alternator | 0 | 3 | \$ 35 | | 0 | | 104 | | 104 |
| 11 | RC12LC4 | Spark plugs | 35 | 35 | \$ 2 | | 59 | | 59 | | 0 |
| 12 | OGU65LD5 | L Door panel (Jeep) | 3 | 0 | \$ 335 | | 1,004 | | 0 | | (1,004) |
| 13 | MKD154 | Brake pads | 2 | 2 | \$ 29 | | 59 | | 59 | | 0 |
| 14 | 472253C1 | Switch blower motor | 6 | 1 | \$ 5 | | 27 | | 5 | | (23) |
| 15 | 52005732 | Cap, wheel center | 8 | 5 | \$ 6 | | 46 | | 28 | | (17) |
| 16 | 5329034 | Relay | 1 | 1 | \$ 70 | | 70 | | 70 | | 0 |
| 17 | 4762489 | Retainer | 33 | 18 | \$ 4 | | 125 | | 68 | | (57) |
| 18 | 4720006 | Jeep blower motor | 4 | 4 | \$ 70 | | 282 | | 282 | | 0 |
| 19 | 18828 | Pittman arm Chevy van | 2 | 2 | \$ 38 | | 75 | | 75 | | 0 |
| 20 | F37Z10047A200 | Console arm Ford Explorer | 3 | 3 | \$ 29 | | 86 | | 86 | | 0 |
| 21 | TA 247 | 6600 Radiator | 1 | 0 | \$ 650 | | 650 | | 0 | | (650) |
| 22 | F77Z19703AB | A/C compressor | 1 | 0 | \$ 160 | | 160 | | 0 | | (160) |
| 23 | P801095 | Adapter linkage | 2 | 2 | \$ 11 | | 23 | | 23 | | 0 |
| 24 | F5DH19497BA | Air compressor | 2 | 2 | \$ 231 | | 462 | | 462 | | 0 |
| 25 | 7127 | Alternator | 3 | 0 | \$ 150 | | 450 | | 0 | | (450) |
| 26 | 4762194 | Axle and shaft assembly | 2 | 2 | \$ 255 | | 511 | | 511 | | 0 |
| 27 | HM88649 | Bearing (front pinion) | 10 | 11 | \$ 17 | | 172 | | 189 | | 17 |
| 28 | 4720006 | Blower motor (Jeep) | 4 | 4 | \$ 70 | | 282 | | 282 | | 0 |
| 29 | XL3Z2200AA | Brakes '98 Expedition | 4 | 4 | \$ 59 | | 236 | | 236 | | 0 |
| 30 | E7TZ99439A00A | Bumper assembly | 13 | 14 | \$ 2 | | 32 | | 35 | | 2 |
| 31 | 2210W7537 | Camshaft, Lf | 3 | 3 | \$ 20 | | 61 | | 61 | | 0 |
| 32 | 2310694 | Carburetor | 3 | 3 | \$ 107 | | 320 | | 320 | | 0 |
| 33 | KN13060 | Compressor | 4 | 4 | \$ 204 | | 815 | | 815 | | 0 |
| 34 | FB59 | Crank case | 4 | 5 | \$ 1 | | 4 | | 5 | | 1 |
| 35 | 26327 | Driveshaft | 5 | 0 | \$ 233 | | 1,165 | | 0 | | (1,165) |
| 36 | 3967 | Fuel pump | 4 | 4 | \$ 42 | | 167 | | 167 | | 0 |
| 37 | 4E600 | Headlight | 3 | 4 | \$ 116 | | 349 | | 465 | | 116 |
| 38 | TA80665 | Hyd motor | 4 | 4 | \$ 412 | | 1,647 | | 1,647 | | 0 |
| 39 | 55036473 | Jeep a/c | 2 | 0 | \$ 197 | | 393 | | 0 | | (393) |
| 40 | F4TZ2140A | Master cylinder & res | 2 | 1 | \$ 102 | | 204 | | 102 | | (102) |
| 41 | PF1250 | Oil filter | 107 | 78 | \$ 3 | | 302 | | 220 | | (82) |
| 42 | MKD477 | Pads for Jeep 93 & 95 | 9 | 0 | \$ 88 | | 790 | | 0 | | (790) |
| 43 | 26037450 | Pump (fuel pump) | 2 | 0 | \$ 339 | | 678 | | 0 | | (678) |
| 44 | F4CZ9C968A | Regulator | 18 | 5 | \$ 34 | | 604 | | 168 | | (436) |
| 45 | D447 | Rotor | 8 | 8 | \$ 3 | | 26 | | 26 | | Ô |
| 46 | 16062 | Shaft assembly | 1 | 0 | \$ 161 | | 161 | | 0 | | (161) |
| 47 | 50844 | Shocks | 36 | 0 | \$ 24 | | 849 | | 0 | | (849) |
| 48 | 1255773 | Solenoid | 11 | 19 | \$ 106 | | 1,164 | | 2,011 | | 847 |
| 49 | 40956 | Splined gear/shaft assembly | 2 | 0 | \$ 116 | | 232 | | 0 | | (232) |
| 50 | J81128900 | Starter | 5 | 5 | \$ 40 | | 198 | | 198 | | 0 |
| 51 | ETTZ9943A00C | Tailgate bumper | 8 | 10 | \$ 2 | | 20 | | 25 | | 5 |
| 52 | F3TZ8501C | Water pump 5.0 Ford | 3 | 2 | \$ 50 | | 149 | | 99 | | (50) |
| - | | 1 1 | - | | Γotal | Φ. | 20,450 | ф 1 | 2,100 | \$ | (8,350) |